

1627Z 7 SEPT 59

TOP SECRET

dpd

DIRECTOR



IPD (1-2-3-4-5-6-7-8)

ROUTINE



S/C (9)

RAS

TOR: 1627Z 7 SEPT 59

IN 460 25X1A

OPIM



K1A

NO NIGHT ACTION

UNSATISFACTORY REPORT

1. LOSS OF OXYGEN, 540 PSI IN 40 MIN, AFTER 6 HOURS OF FLIGHT DUE TO A FAULTY EXHALATION VALVE.
2. DEFECTIVE PART-VALVE, EXHALATION NEV 28A-137.
3. RECOMMENDATION-RETURN TO MANUFACTURE REQUESTING A THOROUGH ANALYSIS OF CAUSE FACTORS IN THE 'INTERMITTENT MALFUNCTION' OF THIS VALVE.

END OF MESSAGE

2 Am

TOP SECRET